



WARNING

THIS ASSEMBLY IS IN THE
CONTROL SYSTEM. REFER
TORQUE SETTING BEFORE INSTALLING IN
PRIMARY TO SIL FOR
AIRCRAFT.

ASSY

REV A-B

618 5999 001

CAUTION

DO NOT VOID WARRANTY.
SERVICE ONLY IN AUTHORIZED
INSTRUMENT SHOPS OR
RETURN TO COLLINS RADIO
COMPANY FOR REPAIR, WHEN
REQUIRED.

SERVO, TRIM

TYPE NO. 334D-6

FAA TSO C9c

DO-138 ENV CAT. AAJAAAEXXXXX

WT 3.6 LB

SER NO.

2594

COLLINS PN 622-0965-

003

Collins Avionics Division/Rockwell International
Cedar Rapids, Iowa 52406 USA