



101-5083

A

Kit No. 101-5083-1 (BB-2 through BB-1203; BL-1 through BL-98; BN-1 through BN-4; BT-1 through BT-30)

The following parts are required:

2039 ✓	Service Bulletin	1 req.
101-910049-133 ✓	Angle	2 req.
101-910049-134 ✓	Angle	2 req.
101-910049-135 ✓	Angle	2 req.
101-910049-136 ✓	Angle	2 req.
101-910049-137 ✓	Angle	2 req.
101-910049-139 ✓	Angle	2 req.
101-910049-140 ✓	Angle	2 req.
101-910049-141 ✓	Reinforcement	2 req.
△ CR3243-4-3 ✓	Rivet	16 req.
101-5083 ✓	Kit Drawing	1 req.

REVISIONS

LTR	DESCRIPTION	DATE	APPROVED
A	Redrawn with changes. Last revision, none. Changes rivet P/N from MS20470AD4 to CR3243-4-3 and removes rivet P/N MS20426AD4. Reason: Change in Part Number Eff: 1st Kit No. 101-5083-1 and after Dis: Rework, Class IIB.	11-22-84	<i>[Signature]</i>

△ P/N of Cherry/Texron Inc. Cherry Commercial Fasteners Products Div. of Textron Inc. 1224 E. Warner St. Santa Ana, CA. 92707

EWO 1041

1	Service Instructions	STANDARD PRACTICE NOTES	CONTR NO. 8602	Beech Aircraft Corporation Wichita, Kansas	
	No. 2039	SEE BEECH STANDARD DRAWING NO. 130450	DR Tim Link		
			CHK <i>[Signature]</i>	Kit - Reinforcement Installation, Air Inlet Screen	
			PROB ENG <i>[Signature]</i>		
-1	101-0101	MATERIAL &/OR PROCESSES	STRUC <i>[Signature]</i>	SIZE CODE IDENT NO. A 70898 101-5083	
			BEECH APPD <i>[Signature]</i>		
			CUSTOMER APPD <i>[Signature]</i>	SCALE None SHEET 1 of 1	
QTY REQD PER ITEM	USED ON NEXT ASSY	MODEL			

90-33546
(WAS E-607-10)