

**FLAP SETTINGS IN EXCESS OF 25° ARE NOT APPROVED.
DISENGAGE THE AIRCRAFT AUTOPILOT PRIOR TO
OPERATING FLAPS.**

**OPERATE FLAP CONTROL IN SMALL INCREMENTS TO
ASSURE FLAP SYMMETRY.**

71934-2