



SERVICEABLE

The component identified above was repaired and inspected in accordance with current Civil Air Regulations and was found airworthy for return to service.

Pertinent details of the repair are on file at this agency under Work Order No. S-8040

Date JULY 28, 1975

Signed [Signature] for

DOWTY ROTOL INCORPORATED

FAA APPROVED REPAIR
STATION NO. 1295

409 JEFFERSON DAVIS HWY.
ARLINGTON, VA.

OVERHAUL / REPAIR DATA

P/N: A3.23802A S/N: 078VI V2 W/O: 8040

Overhauled Repaired Checked O.K. T.S.O. -0-

Findings: No discrepancies

Work Accomplished: Overhauled

Mods. and S.B. Accomplished: AMP Mods M 811 VI4V2, M1375
Mechanic: C. Davis Insp.: C. [Signature] MI

DOWTY ROTOL, INC. RO/322 (OVER FOR ADDITIONAL INFORMATION) C.R.S. #1295