



WARNING TO PREVENT
DAMAGE TO
COMPONENTS CONNECT
COIL LEADS TOGETHER BEFORE
DIELECTRIC TEST

FAA/PMA
EFFECTIVITY
SEE LEACH LIST
512-0023




PERMANENT MAGNET → □

LEACH CORP.
CALIF.
CONTACTOR
CONTACT RATING: 50 AMP
115/200 VAC, 400 Hz, 3Ø
3PST-N.O. WITH
5 AMP AUX. CONTACTS
2 PST-N.C. AND SPST-N.O.
COIL 115 VAC, 400 Hz
LEACH P/N
HD-X9F-011
RECTIFIER & EMI
SUPPRESSION



r Price, Pictures and Availibil
512 370 3718



TORQUING LIMITS
FOR INSTALLATION
#6 7.5 LB.-IN.
#10 24 LB.-IN.
MFR58657-9644



SN 00223



SERVICEABLE PART

OK TO STOCK

Airlines

NEW IRAN

PART NO. HDX9F011

RII 18

NAME RELAY

REF. 23548 SER. NO. NSIV

INSP

DATE 2-28-00 LOT 1

RII 18

Legend

NOT TO BE USED FOR SERIALIZED COMPONENTS IN THE
LEGEND AIRLINES RELIABILITY PROGRAM AND COMPUT-
ERIZED AIRCRAFT MAINTENANCE RECORDS.

224-0111

FORM M-3012
Revision 10-01-99