



OPINIONARY PARTS SUPPLY
WORK ORDER NO. 173935

INSTALLATION CAUTION
ENTER BOLT AS SHOWN (WHERE POSSIBLE)
HOLDING IN THE DIRECTION TENDS TO
TIGHTEN BOLT RATHER THAN UNSCREW
BOLT.
NEITHER ELASTIC STOP NUT NOR COILING
THREADED INSERT HAS DEPENDABLE LOCKING
NECESSARY. IF THE OPPOSITE DIRECTION IS
USED IT WILL WEAR DOWN UNDER BOLT TIGHTENING







P.L. PORTER

Hydrolok®


PART NO. **SL04300 - 08**

REV. **F**

OVH WARRANTY EXPIRES: **07/2007**

WORK ORDER NO: **123935**

ARM



INSTALLATION CAUTION

ENTER BOLT AS SHOW, (WHERE POSSIBLE)
SO
HIGHLOADING IN AFT DIRECTION TENDS TO
TIGHTEN BOLT RATHER THAN UNSCREW
BOLT