AUTHORIZED RELEASE CERTIFICATE FAA/UNITED STATES AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG Consolidated Instrument & Avionics Co FAA CRS# 145 QS2R12			TAG	58740		
10 Industrial Ave, Teterboro, NJ 07	608 USA	FAA CRS# 145 QS2R120L EASA.145.4349			5. Work Order/Contract/ Invoice #: POOO76	
Item 7. Description	8. Part Number	9. Qty:	O. Serial #		11. Status/Work:	
PRESSURE SWITCH 2. Remarks: Refer to Attached Work Order #: 58740	658-7C	4 1	7	7998	OVERHAULED	
Maintenance with Reference to: V.E.P. DWG: 658-7C REV.H MAR	/1992					
Certifies that the items identified above were manufacture Description of the items identified above were manufacture Non-approved design data specified in Block 12. Authorized Spaniere	specified in Bit 14, Code of Fe	ock 12, the wo	k identified in RI	Other regulation specific ock 11 and described in in respect to that work,	block 12 was accomplished in accordance with Tit, the items are approved for return to service.	
Name Typed or Printed: 13e, Date (dd/mmm)		N	MARK JOH	ANNESSEN	14c. Approval/Certificate# QS2R120L 21/0CT/2024 14e. Date (dd/mmm/yyyy):	
Fem 8130-3 (02-14) User/ Installer Respons	sibilities Installer	must cross	check eligibilit	y with applicable ted	chnical data None 0052-03-012-	
Important to understand that the existence of this document alone does not auto- an-worthiness authority of the country specifies to block I, it is essential that the in- 10s and 146 on do consilicte installation cerification. In all cage Details of Work Performed – Work Order Atlanched	maucally constitute authority to install the engine ser/installer ensures that his/her airworthiness au s, aircraft maintenance records must contain an in	urpropeller/article. Vulhority accepts airconstallation certification	where the user/installe raft engine(sypropelle on issued in accordant 8130 Return to Servi	r performs work in accordance r(s /article(s from the airworthin se with the national regulation b se Form, Authorized Sign 43.7	with the national regulations of an arrowal management of the country specified in Block 1. Statements in Bloy the user/installer before the aircraft may be flown. c / 145,157 145,213(a) (b) Attached	
E COPE	TOWN THE		Inspectio	n/Work Rec	ord Form QCF-134	
ONSOLI		Hidden L	amage 🔟 N		e Suspect: see 7. rent/Accidental Damage Results; see wn Inspections: Preservation / Defec	
510 Industrial Ave, Teterboro Airport, Ne Tel: 201-288-1189 • Fax: 201-288-8006 • eMail: sale						
10141 0115211 001 10	ate:	VE	RIFIED DEF	SWITCH#1 NE	UND SWITCH #2 DEFECTIVE; AR FAILURE.	
RO/PO POOO76 Customer PIUS PARTS			S	PRING TENSION	I INCORRRECT.	
Address1: 11 BEE TREE CIRCLE Address2: City: ROCKPORT				OVERHA	UL DUE	
Country: Contact: AE	stal Code: 78382 IE SISSONS 740					
Immendiature: PRESSURE SWITCH						
	TS : 7998					
A/C Mfr. BEECHCRAFT A/C P/N: 101-384119-1	8.	Descrip	tion of Wo	ork Performed	/ Parts Installed	
C Type:: KING AIR ther ID: ,		DISASSEMBLED AND INSPECTED COMPONENTS FOR AGE, LEAKAGE EXCESSIVE WEAR, CORROSION AND OVERHEATING.				
Operation: 2 U.S. GENERAL AVIATION; EASA; U.S. AIRLINE Continuous Airworthiness Program. See 3b.						
EASA & NA. A AD'S:				ADJUSTED SPE	RING TENSION.	
Reason "#2 SWITCH DOES I	NOT OPEN"		DEASSEA	CALIBRATED S	WITCH POINTS. ESTED TO MFR'S SPECS.	
		OVERHAULED & TESTED				
,		1		A	CHARLES JOHNSON	
struction: "REPAIR, OVER	HAUL"	/3		This Article	n Performing the Work e is determined to be airworthy, spect to the work performed.	
			C \ (TO WILLIAM	mnessen/2100 202	
		/ 251	1001	A DETENTION	MMONSUM	