

Repaired/Overhauled by:
Thrust-Tech Aviation, Inc.

Replacement
Plate

IGNITION EXCITER

TYPE
CUST. NO.
P.N. REV.
SERIAL

TX209
3041640-01
9049800-4 C
NN00355906

INPUT
DUTY
REPAIR
STA. NO.

10-30 VDC
CONT.
VKUR 823L

Manufactured By: UNISON INDUSTRIES 59501 Jacksonville, FL USA