WARNING-TO PREVENT DAMAGE TO COMPONENTS-CONNECT COIL LEADS TOGETHER BEFORE DIELECTRIC TEST
FAA/PMA
EFFECTIVITY SEE LEACH LIST 512-0023
MFR58657
11983