101-5083 A

Kit No. 101-5083-1 (BB-2 through BB-1203; BL-1 through BL-98; BN-1 through BN-4; BT-1 through BT-30)

The following parts are requried:

2039	Service Bulletin	1 req.
101-910049-133	Angle	2 req.
101-910049-134	Angle	2 req.
101-910049-135	Angle	2 req.
101-910049-136	Angle	2 req.
101-910049-137	Angle	2 req.
101-910049-139	Angle	2 req.
101-910049-140	Angle	2 req.
101-910049-141	Reinforcement	2 req.
(A) CR3243-4-3	Rivet	16 req.
101-5083	Kit Drawing	1 req.

REVISIONS

LTR	DESCRIPTION	DATE	APPROVED
A	Redrawn with changes. Last revision, none. Changes rivet P/N from MS20470AD4 to CR3243-4-3 and removes rivet P/N MS20426AD4. Reason: Change in Part Number Eff: 1st Kit No. 101-5083-1 and after Dis: Rework, Class IIB.	11-2-82	

(A) P/N of Cherry/Texron Inc. Cherry Commercial Fasteners Products Div. of Textron Inc. 1224 E. Warner St. Santa Ana, CA. 92707

EWO 1041

QTY REQD PER ITEM	USED ON NEXT ASSY	MODEL
1	Service Instructions No. 2039	200
		B200
-1	101-0101	200C
		B200C
	200T	200CT
	B200T	B200CT

STANDARD PRACTICE NOTES: SEE BEECH STANDARD DRAWING NO. 130450

MATERIAL &/OR PROCESSES

CONTR NO.	8602
DR	Tim Link
CHK	
PROJ ENGR	
STRUCT	1-15
BEECH APPD	
CUSTOMER APPD	

Beech Aircraft Corporation
Wichita, Kansas

Kit - Reinforcement Installation, Air Inlet Screen

SIZE	CODE IDENT NO.	
A	70898	101-5083

SCALE None SHEET 1 of 1

90-33546 (was E-407-10)