

REJECTED PARTS TAG

FORM 5

AERO SKY AIRCRAFT MAINTENANCE
2030 First Ave., Hangar 4
San Antonio International Airport
San Antonio, Texas 78216
FAA CRS KQ7R556N / EASA 145.6281

Registration: N524TP Date: 10/20/20

Manufacturer: UNK

Identifiaction: Flap POS Tradsmitter

Part Number: 18-1738-9 Serial No. UNK

QTY: 1 TSO: UNK Location: R/H

Discrepancy: right Needle pops back to 30° from 40° pos

Rejected by Inspector (Printed Name) MAX Hickerson

Signature: Max Hickerson

24