

Nº 33311

KING

Newly Overhauled

EXCHANGE ASSEMBLY

Part # 200-1718-05 Rev 44

FROM: Mods 1+3

Check One: Exchange Allowance ☐ Replace Assembly ☐

Note: If product warranty applies

Warranty Claim # _____

to accompany defective assembly.

— INSTRUCTIONS —

For exchange eligibility both sides of this tag must be completed and the top portion attached to the identical defective assembly being returned.

Return to:
King Radio
Warranty Dept.
400 N. Rogers Rd.
Olathe, Kansas 66061

Nº 33311 EXCHANGE ASSEMBLY KING

Part # 200-1718-05 Rev 44

Mods 1+3

AVIONICS CENTER

LOCATION

RETAIN THIS STUB FOR RECORD