PMI
SC-2
FINAL
C.A.
SSI
ACC #2
JUN 1 0 2003
TV ANTENNA
PART NO. S65-8282-21
SERIAL NO. 1091
TSO C37b, C38b WT. 2.3 LBS.
DO-160A ENV. CAT. F2BJERHDFSAAAAA
SENSOR SYSTEMS® INC.
CHATSWORTH, CA. USA
FSC 13691

1. Approving Civil Aviation Authority/Country:	2 AUTHORIZED RELEASE CERTIFICATE	3. Form Tracking Number:
FAA/United States	FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	534543

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
PK4R443M Avionics Specialist, Inc. 3833 PREMIER AVENUE MEMPHIS, TN 38118 U.S.A. Phone (901) 362-9700 Fax (901) 375-8310 WWW.AVIONICS-SPECIALIST.COM	P00700

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
A	SENSOR SYSTEMS AM/FM TV ANT S65-8282-21	S65-8282-21	1 each	1091	INSPECTED/TESTED

12. Remarks: Approval For Return To Service Reference Work Order: 534543 Technician: Chris Lambert Date: 20 OCT 2025

TESTED AND INSPECTED ANTENNA. UNIT PASSES PERFORMANCE TESTS. CLEANED ANTENNA OUTER SURFACE. ANTENNA MEETS ALL MFG. SPECS. ANTENNA HAS BEEN BENCH CHECKED AND INSPECTED USING CMM. # 523-0769094, 3RD. EDITION, NOV. 23, 1992. UNIT HAS NO SERVICE BULLETINS. ANTENNA APPEARS TO BE IN NEW SURPLUS CONDITION.

All personnel associated with the repair of this part/component met the requirements of FAR 121.377. This document has been issued according to an FAA accepted electronic signature process 09/2017. Avionics Specialist, Inc. certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Certificate Number EASA.145.4220.

13a. Certifies the items identified above were manufactured in conformity to:	14a. ☑ 14 CFR 43.9 Return to Service ☑ Other regulation specified in Block 12
☐ Approved design data and are in a condition for safe operation ☐ Non-approved design data specified in Block 12	Certifies that unless otherwise specified in block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations; part 43 and in respect to that work, the items are approved for return to service.
13b. Authorized Signature	13c. Approval/Authorization No:
13d. Name(Typed or Printed):	13e. Date (dd/mmm/yyyy):
14b. Authorized Signature Mark G Dahler	14c. Approval/Certificate No.: PK4R443M
14d. Name(Typed or Printed:) MARK G. DAHLER	14e. Date (dd/mmm/yyyy:) 20 OCT 2025

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.