HSi CONTROL PANEL
TYPE NO. HCP-74
TSO C6c, C52a, C40b
(SEE INST. BOOK)
DO-160A ENV CAT. /A2C1/B/PKS/XXXXXXAXXXA
WT .6 LB
S/N 767
COLLINS PN 622-6200- 003
Rockwell Collins, Inc.
Cedar Rapids, Iowa 52498 USA/Mfd Melbourne, FL
3 4 5 6 8 10 A B C

1. Approving National Aviation Authority/Country: FAA/United States

2.

AUTHORIZED RELEASE CERTIFICATE

FAA FORM 8130-3,AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number: 102757389

4. Organization Name and Address: Rockwell Collins Sales & Services, Inc.
5159 Southridge Parkway
ATLANTA,GEORGIA 30349 USA HB4R226M

5. Work Order/Contract/Invoice Number: PO No: C210000870

6. Item:	7. Description:	8. Part Number:	9. Eligibility:*	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
000010	HCP-74 / HCP-74 HSI C	622-6200-003	N/A	1	767	REPAIRED

13. Remarks:
Serviced IAW EO # N/A.
S.B.s installed: N/A.
CW A.D.: N/A.
Tested Per: 523-0772704-0A311A ED. 3 TEMP.REV. 10
Refer to attached Service Memorandum (referenced in block 3 above) for service details.

Air Data products have been tested and inspected and found to comply with F.A.R. 91-411 (Ref Part 43 App. E).
ATC transponders have been tested and inspected and found to comply with F.A.R. 91-413 (Ref Part 43 App. F).
"Rockwell Collins Atlanta Service Center certifies that the work specified in block 12 and 13 was performed in accordance with EASA implementation Rule part 145 approval, and with respect to that work, the aircraft component is considered ready for release to service under EASA 145 approval number: EASA.145.4333."
Item Numbers refer to numbers on Delivery Document

14. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in block 13.

N/A

19. [X] 14 CFR 43.9 Return to Service [X] Other regulation specified in Block 13

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13, was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

15. Authorized Signature:

16. Approval/Authorization:

17. Name (Typed or Printed):

18. Date (m/d/y):

20. Authorized Signature: Matthew A. Neelley

21. Approval/Certificate No.: HB4R226M

22. Name (Typed or printed): Matthew A. Neelley

23. Date (m/d/y): MAY/21/2007

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1.

Statements in block 14 and 19 do not constitute installation certification. In all cases, aircraft maintainence records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

*Installer must cross-check eligibility with applicable technical data