

LIBRIS AERO-TECHNIK-
GMBH 9893

P/N
MOD.
S/N
INSP.

10124

FLUID

DAT.

10.2

FLAP ACTUATOR

28CG 2/11

REPAIRABLE PART TAG

W.O. No. _____

Equipment: Name _____

Type _____ Serial No. 124

Part Name Flap Actuator Part No. 1048A0000-04

Remarks: _____

Leaks due to overspray on cylinder

Date 4/29/15 Inspector [Signature]

CORNING AVIATION

348 Sing Sing Road • Horseheads, N.Y. 14845

CRS IH1R218K

REPAIRABLE