

ROLL TRLM. ACTUATOR

Ref (P/N)	8410-1	N° (S/N)	424
Date	10/01	Cle (insp)	
AVIAC	F0396	Amend ^t	

REPAIRABLE

Myrtle Air Services, Inc.
1114 Airdrome Ave
Myrtle Beach, SC 29577

COMPONENT/PART Roll trim
Actuator

P/N 84-10-1

S/N 424

MFG AviAc

A/C/ENG/COMP# _____

DATE 16 July 2021

W.O.# 100333

(IF REQUIRED)

REASON FOR REMOVAL AND/OR

DAMAGE NOTED Moist indicator

INITIATED BY PMD 5059

MASI M-005 CRS #6MYR388D REV. 0