



14MM FBR ACTUATOR

Ref (P/N) 2408-2 N° (S/N) 183

Date 07-95 C° (insp) 

AVIAC F0396 Amend' 



REPAIRABLE PART TAG

14809

W.O. No. _____

Equipment: _____

Name Aviac

Type Dornier 328

Serial No. 183

Part Name Rudder Limiter

Part No. 8428-2

Remarks: _____

Removed from N380X due to
wire bundle being damaged and desiccant indicator
being NOT Blue.

Date _____

10/31/17

Inspector _____



CORNING AVIATION

348 Sing Sing Road • Horseheads, N.Y. 14845

CRS 1 H 1 R 2 1 8 K



