



DO NOT OPEN BAG UNTIL FASTENERS ARE TO BE USED
Contents may become contaminated or lose their lubricant, which
may affect their performance.

IMPORTANT:
"BLIND FASTENERS ARE NOT ALWAYS INTERCHANGABLE WITH
NON-BLIND FASTENERS. CONSULT WITH THE AIRCRAFT OR
EQUIPMENT MANUFACTURER FOR PROPER APPLICATION OF THIS PRODUCT."

ACCEPT NO SUBSTITUTES™

BACR15FR4B9R

FAA-TSO-C148

CR3243-4-09

FAA-TSO-C148

LOT # 86070077



Hole .143 .146

Grip .501 .562

QTY



Nov 2001

ALSO IN FULL COMPLIANCE WITH THE
FOLLOWING NON-TSO PART NUMBER(S)

NAS9304B-4-09

NAS9304BNS-4-09

M7885/6-4-09

TEXTRON Aerospace Fasteners

A Unit of Textron Fastening Systems

1224 East Warner Ave., Box 2157

Santa Ana, CA 92707-0157

www.taf.textron.com

Phone 714-545-5511

FSCM 11815