



OBrien Ent.  
562-988-9546

|    |    |    |
|----|----|----|
| 3  | B5 | 26 |
| MO | 82 | YR |

Signal Hill, CA

**NEXT HYDRO DUE**

|      |      |    |   |
|------|------|----|---|
| YEAR | 2029 | MO | 3 |
|------|------|----|---|

**OBRIEN ENTERPRISES**  
Signal Hill, CA  
562-988-9546

8321



**O'Brien Enterprises**

2420 E. 28th Street, Suite 2  
Signal Hill, California 90756  
Tel: 562-988-9546  
Email: sobrienenterprises@gmail.com

WORK ORDER NO. **HY 28010**  
D.O.T. #B528

**HYDROSTATIC TEST FINDINGS AND COMPLETION REPORT**

Customer: Pius Parts Date Received 18 Mar 2026  
 Address: Rockport Units Received this P.O. 1  
 P.O. #: PO0977 Unit 1 of 1 Units. Page 1 of 2 Pages  
 Mfg. Part Number: 212940-2 Assembly Serial #: 8391  
 Other Part Number: 9912103-3 Cylinder Serial #: 71197 B1  
 Manufacturer: Kidde  HTL/PacSci  Scott  Puritan  B/E  Tavco  Av-Ox  Sota   
 Aerox  Precise Flight  ITT  Other  Valve P/N # \_\_\_\_\_  
 Description: 02 Cylinder  N2 Cylinder  Other \_\_\_\_\_ Valve(s) Serial # \_\_\_\_\_

**REASON FOR RETURN**

Hydrostatic Test  Other: \_\_\_\_\_  
 Repair  \_\_\_\_\_  
 Recharge  \_\_\_\_\_  
 Service Regulator  \_\_\_\_\_

**INITIAL INSPECTION**

Date of Mfg: 07-2014 Size: 90 C.F.  TEST PRESSURE 4800 P.S.I.  
 Last Hydro: 05-2023 C.I.  Other Information: \_\_\_\_\_  
 DOT Rating: 8162-1850  Non-DOT Cylinder   
 3AA1800  Other \_\_\_\_\_ Full   
 3HT1850  Empty   
 10945-1850   
 3AL \_\_\_\_\_  
 Parts Missing: None  Safety Cap(s)  Valve(s)  Fittings  3 φ Other: \_\_\_\_\_  
 Additional Parts Received: None  Safety Caps  Strap/Clamp  Mask  Other: \_\_\_\_\_  
 Exterior Condition: Good  Fair  Poor  Comments: \_\_\_\_\_  
 Interior Inspection: Pass  Fail  Hidden Damage: None  Comments: \_\_\_\_\_  
 Repairable: Yes  No  BER/Scrap: Yes  No   
 Serviced per Mfg: HTL/PacSci  Kidde  DOT/CFR49  Other: \_\_\_\_\_  
 Serviced I.A.W. Customer Procedures Manual: Yes  No  Manual # 36-10-03 Rev. 11-2003  
 Other: \_\_\_\_\_

**CORRECTIVE ACTION**

Hydrostatic Test  Scope of Work: \_\_\_\_\_  
 Inspect Interior  Repaired   
 Refinish Ext.  Recharge   
 Wt. and/or Leak Test  No Work Done   
 Inspect and Condemn