



O'Brien Enterprises
 2655 E. Green Street, Unit # 7
 Phoenix, AZ 85034
 Tel: 602-944-9444
 Fax: 602-944-9444
 E-Mail: info@obrien.com

Website: www.obrien.com
 Part # 2655E72025

Customer: Redshift TX
 Address: Redshift TX
 Part # 164396 C1

Customer ID # P00073
 Part Number 32700015
 Other Part Number N/A
 Manufacturer Status HTU/HTDU AM/MTK Other
 Description: Fire Extinguisher Other

Weight and Leak Test
 Hydraulic Test Inspect Interior
 Repair Other

INITIAL INSPECTION

Date of Mfg. 08-1995 Year 1995
 Last Original 09-2020 Capacity 40 PSI 60 PSI 80 PSI 90 PSI 120 PSI
 #1 Cartridge Date 09/2019 None 168 C.I. 224 C.I. Other Cap.
 #2 Cartridge Date 09/2019 None Test P.S.I. 1680 1800 2000 2100 3000
 #3 Cartridge Date / None Recycled: Fail Empty Fused Low P.S.I.

INITIAL INSPECTION ANALYSIS

Parts Missing: None Cartridge(s) Discharge Outlets Safety Cap Helon/NG Other
 Additional Parts Received: None Safety Data Stamp/Clamp Other
 Exterior Condition: Good Poor Other 1 cartridge damaged in transit
 Interior Inspection: Pass Fail Hidden Damage: Yes No Comment

Repairable: Yes No BEF/Scrap: Yes No
 Serviced per Mfg. HTU/HTDU NFR/10 Other Manual # 26520-302 Rev. # 8-1-2017
 Serviced IAW Customer Procedures Manual: Yes No
 Other Findings: No Activity Other

CORRECTIVE ACTIONS

Overhaul IAW Mfg Specs Inspect Interior
 Repaired IAW Mfg Specs Refinish Exterior
 Recharge - Mt. and/or Leak Test No Work Done
 Hydrostatic Test IAW DOT/CFR49 PART 180.2

Scope of Work: Inspected and test pressure switch Yes No

Rev. Date 08-21-2008
 S.O. 123.04

A1
656
65310
A1

CAGE CODE: 85167

PACIFIC SCIENTIFIC HTL/Kin-Tech Division

FIRE EXTINGUISHER

PAT. NO. 3,552,495
HTL P/N 32700015
SERIAL NO. 14447C1
AGENT (CBrF₃) 4.00 LBS
PAT. NO. 3,129,765

CHARGE DATE	GROSS	WEIGHT LBS
6-10-15	7.98	
7-9-22	7.92	
9-25-28	7.73	

WITH WITHOUT CARTRIDGE

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 25-30768	
4. Organization Name and Address: OBrien Enterprises - 2420 East 28th St. - Signal Hill CA 90755 (QK3R792L)				5. Work Order/Contract/Invoice Number: 29799		
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	Fire extinguisher	32700015	1	14436 C1	Overhauled	
12. Remarks: Overhauled in accordance with approved data, CMM 26-20-202 , REV 08-01-2019 Inspect, clean, hydrostatic test, repair as required, refill and leak test . Cartridge Info: P/N AE 13083-5, Serial # 1117 D.O.M. 09-2019 AE 13083-5, Serial # A7269, D.O.M. 8-2025 Inspect and test pressure switch: N/A Other P/N: N/A Last Overhaul 09-27-2025 Next overhaul due 09-27-2030						
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.			14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature: XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX		13c. Approval/Authorization No.: XXXXXXXXXXXXXXXXXXXXXXXXXXXX	14b. Authorized Signature: 		14c. Approval/Certificate No.: QK3R792L	
13d. Name (Typed or Printed): XXXXXXXXXXXXXXXXXXXXXXXXXXXX		13e. Date (dd/mmm/yyyy): XXXXXXXXXXXXXXXXXXXX	14d. Name (Typed or Printed): Sid OBrien		14e. Date (dd/mmm/yyyy): 18NOV2025	
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

X

X

O'Brien Enterprises

2420 E. 28th Street, Unit 2
Signal Hill, California 90755
Tel: 562-988-9546
Email: sobrienenterprises@gmail.com
F.A.A. # QK3R792L

WORK ORDER NO. 29799

INSPECTION AND TEARDOWN REPORT

Customer Pius Parts Date Received 24SEP2025
 Address Rockport TX Units Received this P.O. 2
 Unit 2 of 2 Units
 Customer P.O. # P00673 Assembly Serial # 14436 C1
 Part Number 32700015 Cylinder Serial # _____
 Other Part Number N/A Other: _____
 Manufacturer: Kidde HTL/PacSci AMEREX Other _____
 Description: Fire Extinguisher Other _____

CUSTOMER REQUESTS

Overhaul Weight and Leak Test
 Hydrostatic Test Inspect interior
 Repair Other _____
 Refill _____
 Inspect and test pressure switch Yes No **N/A**

INITIAL INSPECTION

Date of Mfg. 08-1995 DOT Rating: 4D _____ 7945- 700 _____ Other _____
 Last Overhaul 06-2020 Capacity: 60 C.I. 86 C.I. 90 C.I. 125 C.I.
 #1 Cartridge Date: 09 /2019 None 195 C.I. 224 C.I. Other Cap. _____
 #2 Cartridge Date: 09 /2019 None Test P.S.I. 1600 1800 2000 2100 2400 3000 Other _____
 #3 Cartridge Date: _____ / _____ None Received: Full Empty Fired Low P.S.I.

INITIAL INSPECTION ANALYSIS

Parts Missing: None Cartridge(s) Discharge Outlet(s) Safety Cap(s) Halon/N2 Other: _____
 Additional Parts Received: None Safety Caps Strap/Clamp Other _____
 Exterior Condition: Good Fair Poor Other 1 cartridge damaged in transit
 Interior Inspection: Pass Fail Hidden Damage: Yes No Comment _____

Repairable: Yes No BER/Scrap: Yes No
 Serviced per Mfg: HTL/PacSci Kidde NFPA10 Other _____
 Serviced I.A.W. Customer Procedures Manual: Yes No Manual # 26-20-202 Rev. Date 08-01-2023
 Other _____ Rev. # 8-1-2019
 Investigate A.D. Activity: Yes No By Sid O Findings: No Activity Other: _____

CORRECTIVE ACTIONS

Overhauled IAW Mfg Specs Inspect Interior Scope of Work: Inspect and test pressure switch Yes No **N/A**
 Repaired IAW Mfg Specs Refinish Exterior
 Recharge - Wt. and/or Leak Test No Work Done
 Hydrostatic Test IAW DOT/CFR49, PART 180.2

