		vionics Specialist, Inc. K4R443M	3833 Premier Av Phone (901) 362	, , , , , , , , , , , , , , , , , , , ,	,		5.	. Work Order/Contract/I
6. Item:	7. Description:	8. Part Number:	9. Eligibility: *	10.	Quantity	11. Serial/Batch	Number:	12. Status/W
A	KING KTR953	064-1015-00	N/A	1	each	4153		REPAIRED
Certifies Appr	a. ASSOCIATED WITH THE REPAIR OF THE conflict had the work provided in block 1973 was our the Herms identified above were ma aged design data and are in a condi- approved design data specified in I	ried out in accordance with EASA Part-145 and with or unufactured in conformity to: tion for safe operation.	EMENTS OF FAI's 121.377. respect to that work the aircraft comports	19. X 14 CFR 43.9 Certifies that described in	Return to Service t unless otherw Block 13 was		Other regulation ock 13, the work	Title 14, Code of Fe
Certifies App	the lieus identified above were ma swed design data and are in a condi-	ried out in accordance with EASA Part-145 and with or unufactured in conformity to: tion for safe operation.	espect to that work the alicraft comport	19. X 14 CFR 43.9 Certifies that described in	P Return to Service t unless otherw Block 13 was part 43 and in	vise specified in blo accomplished in ac	Other regulation ock 13, the work	c identified in Bloc Title 14, Code of Fe approved for return entificate No.:
Appro Non	e ordine but to work spooled to book 12/13 was on the Hems Identified above were ma ayed design data and are in a condi- approved design data specified in I	inducting accordance with EASA Part 45 and with insuffactured in conformity to: tition for safe operation.  Slock 13.	espect to that work the alicraft comport	19. X 14 CFR 43.9 Certifies that described in Regulations;	Printed):	vise specified in blo accomplished in ac respect to that wor	X Other regulation ock 13, the work coordance with 7 k, the items are	c identified in Bloc Fitle 14, Code of Fe approved for return entificate No.: 43M

CS see