

SERVICEABLE

32-07
RAYTHEON AEROSPACE
2300 HORIZON DRIVE
FORT WORTH, TEXAS 76177
FAA CRS R29R0290

MAINTENANCE RELEASE


The aircraft, airframe, engine, propeller or appliance identified herein was repaired and inspected per current Federal regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair and inspection are on file at this repair station under

WORK ORDER

1-1369

INSPECTOR

Kennard 11/13/01



Part # or Model

065-0040-00-R04

Nomenclature

KS 273

Serial Number

1309

Total Since New

Time Since Overhaul

Cycles Since New

Cycles Since Overhaul

Repairs accomplished Visually Inspected.

Removed IN serviceable Condition A/c 21062582

Technician

R. Lewis

Code

9D ATA 27-40-03

Date

11-13-01

FORM RASSOO11

065-0040-00-R

KS 273 TRIM SERVO

P/N 065-0040-00

TSO C9: D0138 EHV CAT BAJAAAXXXXXX

S/N 1309

MAX DC INPUT - MV 5A.28V/5A

WT. 2.2 LBS.

KING RADIO CORP.

TRIM
SERVO