

100-364217-9 ANNUNCIATOR FAULT DETECTION SYSTEM

Beech Aircraft Corporation
Wichita, Kansas 67201

P/N 100-364217-9 QTY. 1
NAME R.C. Board S/N 642-A-78
DISTB. Trilanna Beech GR 108588
A/C SERIAL _____ W/C NO. _____

WARRANTY R50#
REPAIR 46805
EXCHANGE
DATE 11-1-78

RETURNED CUSTOMER PROPERTY

32-34221

WORK ORDER/MAINTENANCE RELEASE
BEECH AIRCRAFT CORPORATION, WICHITA, KANSAS, 67201, USA

PART NAME R.C.B. MODULE ASSY. PART NO. 100-364217-9
MAKE BEECH AIRCRAFT MODEL 200 S/N 642-A-78

THIS PART WAS: REPAIRED, REBUILT TO ZERO TIME,
 OVERHAULED, FUNCTIONALLY TESTED, ALTERED
AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS
OF THE FAA AND IS APPROVED FOR RETURN TO SERVICE.
PERTINENT DETAILS OF THE WORK ACCOMPLISHED ARE ON FILE
AT THIS REPAIR STATION UNDER W.O./R.S.O. NO. R\$0-46805.

Jerry R. Longle 10-30-78 C.R.S.334
AUTHORIZED SIGNATURE DATE C.R.S.334A
Pending M.M.F.3345
CERTIFICATE NO.

Form No. 78-37056