

Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country 12. Remarks: Approval For Return To Service Reference Work Order: 530650 Technician: Lee Martin Date: 05 NOV 2025
TESTED AND INSPECTED ANTENNA UNIT PASSES ALL PERFORMANCE TESTS. CLEANED, REPAIRED AND REFURBISHED ANTENNA OUTER SURFACE. ANTENNA MEETS ALL MFG. SPECS. ANTENNA
HAS BEEN REPAIRED USING CMM. # 523-0769083, 2ND, EDITION, 15, SEPT. 1983. UNIT HAS NO SERVICE BULLETINS INDICATED. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. 6. Item: specified in Block 1. 136 Authorized Signature I. Approving Civil Aviation Authority/Country: Organization Name and Address personnel associated with the repair of this part/component met the requirements of FAR 121.377. This document has been issued according to an FAA accepted electronic signature process 09/2017. Avionics Specialist, Inc. certifies that the work became in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Certificate Number EASA 145.4220. **FAA/United States** rtifies the items idertified above 17-50-01 TRIVEC-AVANT ANTENNA Description: Avionics Specialist, Inc. were manufactured in conformity to: PK4R443M AUTHORIZED RELEASE CERTIFICATE 13e. Date (dd/mmm/yy 13c. Approval/Authorization No. FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG 17-50-01 8. Part Number: 3833 PREMIER AVENUE MEMPHIS, TN 38118 U.S.A Phone (901) 362-9700 Fax (901) 375-8310 WWW.AVIONICS-SPECIALIST.COM User/Installer Responsibilities 14a. 14d. Name(Typed or Printed:) 14b. Authorized Signature MARK G. DAHLER and described in Block 12 was accomplished in accordance with Title 14, Code of Certifies that unless otherwise specified in block 12, the work identified in Block 11 return to service. Federal Regulations; part 43 and in respect to that work, the items are approved for 14 CFR 43.9 Return to Service March G Saller 9. Quantity: 1 each 2062 10. Serial Number: Other regulation specified in Block 12 14e. Date (dd/mmm/yyyy:) 14c. Approval/Certificate No. 05 NOV 2025 PK4R443M 5. Work Order/Contract/Invoice Number: P00516 3. Form Tracking Number: 530650 REPAIRED 11. Status/Work:

national regulations by the user/installer before the aircraft may be flown