


REPAIRABLE TAG

Jetran LLC.
1449 Airpark
Horseshoe Bay Tx. 78657

Customer Name: Jetran Aircraft S/N. 512
Aircraft Reg. 900J
Part Name: Signal Conditioner
P/N: 555-049-003 Rev F
S/N: 179
Aircraft TAT: _____ Aircraft TAC: _____
Reason for Removal/notes: Failed
Mechanic: WAW A & P #: _____
Date: 4/20/21

J1



J2



J7



J3



J4



J5



J6



Parker Hannifin Corporation
Gull Electronics Systems Division
300 Marcus Boulevard
Smithtown, NY 11787
516-231-3737, Fax 516-434-4706
FAA Approved Repair Station # FX1R156K

Parker Hannifin Corporation
Gull Electronic Systems Div.
Smithtown, N.Y. 11787
367-933-002
SIGNAL CONDITIONER
SERNO 179 WTS. 60LBS TYPE II
RATING 28 VDC APVD FOR TSO-C55
0-20,000 LBS 0-9990 KGS
0-20 PINTS

AUG 31 2003

JUL 01 2004

MODIFICATIONS
1 2 3 4 5 6 7 8 9 10
11 12 13 14 15 16 17 18 19 20 21

SOFTWARE CONTROL RECORD
PART NO. 555-049-003 REV. F

J5

Parker
Parker Hannifin Corporation
Gull Electronics Systems Division
300 Marcus Boulevard
Smithtown, NY 11787
516-231-3737, Fax 516-434-4706
FAA Approved Repair Station # FX1R156K

Parker Parker Hannifin Corporation
Gull Electronic Systems Div.
26055 Smithtown, N.Y. 11787
PN 367-933-002
SIGNAL CONDITIONER
SERNO **179** WT **5.60LBS** TYPE **II**
RATING 28 VDC APVD FOR **TSO-C55**
0-20,000 LBS 0-9990 KGS
0-20 PINTS

MODIFICATIONS
● 1 2 3 4 5 6 7 8 9 10
11 12 13 14 15 16 17 18 19 20 21

SOFTWARE CONTROL RECORD
PART NO. **555-049-003** REV. **F**

JUL 01

