



SERVO MOTOR
91051340

SERVO MOTOR PART NO. 4005679-1
SERIAL NO. 91045456
1.7 LB TSO C90

Tamagawa
TS3114N1-E24
S/N A3279 DATE 10.1990
PART NO. 4005679-1
TAMAGAWA SEIKI CO. LTD. JAPAN

Honeywell

SM-200

SERVO DRIVE

PART NO. 4006719-906

SER NO.

91045456

WT 4.7 LB TSO C9c

MOD

| | | |
|---|---|---|
| G | H | J |
| K | L | M |

PHOENIX, ARIZONA, U.S.A.

SERVICEABLE TAG

Jetran LLC.
1449 Airpark
Horseshoe Bay Tx. 78657

Customer Name: _____ Aircraft S/N. N500VL

Aircraft Reg. _____

Part Name: 4006719-906

P/N: servo

S/N: 91045456

Aircraft TAT: _____ Aircraft TAC: _____

Reason for Removal/notes: _____

Mechanic: Hugo A & P #: _____

Date: 16 June 2021