




SERVICEABLE

WO#: G1-5 N#: N23176

Description: Turn coordinator

Mfr: — Model: TC120-1A

P/N: 507-0020-902 S/N: M2943

Remarks: —

— As Removed — Repaired — Overhauled ☒ Function Tested — Inspected

Removed By: Sebastian Richard Date: 8-21-2015

JLC
avionics

JLC Avionics, LLC
CRS: 9JAR368B