

1. Approving National Aviation Authority/Country:
FAA/United States

AUTHORIZED RELEASE CERTIFICATE
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

PAGE: 1 OF 1

3. Form Tracking Number

4. Organization Name and Address:

Rockwell Collins, Inc.
2051 Airport Road
WICHITA, KANSAS 67209-1949 USA

NZ2R049L

5. Work Order/Contract/Invoice Number:
PO No: 5900017226

102366022

6. Item:	7. Description:	8. Part Number:	9. Eligibility:	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
000010	3-D FLIGHT DIRECTOR INDICATOR	622-0836-002	N/A	1	903	REPAIRED

13. Remarks:

Refer to Service Memorandum (referenced in block 3 above) for service details.

Tested Per: TSP 209 Rev. D, Maintained Per: 523-0763457 Ed.1 Rev.4, TSO: N/A

S.B.s installed:

Complied with A.D. #: N/A ...

A/C identification: 35A-110, Total Cycles: 7619, Total Time: 10393.6, as per customer supplied document.

Rockwell Collins Wichita certifies that the work specified in Blocks 12 and 13 was performed in accordance with EASA Implementation Rule part 145 approval, and with respect to that work, the aircraft component is considered ready for release to service under EASA approval number 145.4334.

Item Numbers refer to numbers on Delivery Document

14. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation

☐ Non-approved design data specified in Block 13

N/A

19. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 13

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13, was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

15. Authorized Signature:

16. Approval/Authorization:

20. Authorized Signature:

21. Approval/Certificate No.:

NZ2R049L

17. Name (Typed or Printed):

18. Date (m/d/y):

22. Name (Typed or printed):

Richard A. Kostner

23. Date (m/d/y):

FEB/27/2006

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1.

Statements in block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA FORM 8130-3 (6-01)

*Installer must cross-check eligibility with applicable technical data

NSN: 0052-00-012-9005

INDICATOR, FLIGHT DIRECTOR

TYPE, NO. 329B-7R-2 TSO C3b, C4c, C52a
DO-138 ENV CAT. GAPAAAXXXXX
26 V AC 400 HZ -25 VA 5 V AC/DC -1.2 A
BANK 360° PITCH $\pm 90^\circ$

WT 5.0 LB SER NO. 903

COLLINS PN 622-0836-002

Collins Avionics Division/Rockwell International
Cedar Rapids, Iowa 52406 USA



J1

