



Turn Selector Switch to BAT
(2) If equipped with BAT
(3) If pointer does not zero, replace null indicator batteries.
For Circuit:
(1) Turn Selector Switch to a measuring
(2) If equipped with BAT, rotate fully clockwise
(3) Rotate ZERO pointer to zero
BAT cannot be zeroed, replace null indicator batteries.

Asset number AR1 1628 Serial # 1628
Card by U AR 901-259-9001
Last calib 8/25/2011 Next calib 8/25/2012



OFF BAT CHK
.01 1000
1 10 100
MULTIPLIER

ZERO
ADJ



OHM

OFF ON
BAT DET

KELVIN BRIDGE

BIDDLE INSTRUMENTS



MADE IN U.S.A.

USE ONLY IN ACCORDANCE
WITH INSTRUCTION MANUAL