

UK CAA	Z. AUTHORISE	RELEASE CERTIFICATE ASA FORM 1		cking Number 7324-10300
T	MEGGITT AEROSPACE LIMITED F/A MEGGITT AIRCRAFT BRAKING SY dolbrook Lane, Coventry CV6 4AA, England. Felephone: (024) 7666 6655. Fax: (024) 766		5. Works Order/Contract or Invol Notification: 35001 PO: RO-4059	ce No. 9268
1,	8.	9. Qty	Serial No.	Status / Work
tem Description	Part No.	1	(0059)	REPAIRED
10300 BM UNIT				
that work, the items are approved to IOD STATUS: MOD 1	ding to an approved computer generates signature pro- 22 was accomplished in accordance with Title 14, code or return to service under Title 14, code of Federal Reg =C/21/2007	ulations, part 43 Approval Number D9	BY398N. HORSEHEADS NY 14845 USA	
that work, the items are approved to IOD STATUS: MOD 1 WW CMM 32-42-04 REV 1 DATED DE	or return to service under Title 14, code of return Reg	ulations, part 43 Approval Number D9	NY 14845 USA	regulation specified in Block 12
that work, the items are approved to IOD STATUS: MOD 1 AW CMM 32-42-04 REV 1 DATED DE	shave were manufactured in conformity to	14a. 🔀 Part-145.A.50 R Certifies that unless otherw described in Block 12 was	NY 14845 USA	regulation specified in Block 12
that work, the items are approved to IOD STATUS: MOD 1 AW CMM 32-42-04 REV 1 DATED DE 3a. Certifies that the items identified a approved design data and are in non-approved design data specification.	shave were manufactured in conformity to	14a. 🔀 Part-145.A.50 R Certifies that unless otherw described in Block 12 was	NY 14845 USA elease to Service X Other r ise specified in Block 12, the work accomplished in accordance with F accomplished in service	regulation specified in Block 12
o that work, the items are approved to JOD STATUS: MOD 1 AW CMM 32-42-04 REV 1 DATED DE JOS STATUS STATES STAT	above were manufactured in conformity to condition for safe operation	14a. Part 145.A.50 R Certifies that unless otherwidescribed in Block 12 was work the items are conside 14b. Authorised Signature C. Philpott. 14d. Name CLIVE PHILPOTT	NY 14845 USA elease to Service X Other is sespecified in Block 12, the work occomplished in accordance with Fed ready for release to service	regulation specified in Block 12 cidentifed in Block 11 and Part -145 and in respect to that Lic. Certificate/Approval Ref No. UK.145.00693 e. Dete (dd mmm yyyy) 11/APR/2011

MEGGITT

MRO WORKSHOP REPORT

Unit Part No AC70071

Serial Number. 0059 Mod State, 1.

Notification No. 45011371

Equipment # No 10131223

Documentation Reference. 32-42-04

Reason for removal: "LEFT VALUE FAIL" LET ON ANTI-SKID COMPUTER

Unit tested prior to strip YES MOUNT

Test satisfactory

MARS / NO

Comments: FAULT CONFIRMED, LEFT HAND TWIN COIL ASSY RECORDED OPEN CIRCUIT. NEW TWIN COIL RETURNED PLUS ANY SPALS DISTURBED.

Technician



CORNING INCORPORATED

DASF 115 Issue 1

Meggitt Aircraft Braking Systems Holbrook Lane, Coventry, CV6 4AA, UK