



Orlando-Sanford Int'l Airport  
2789 Flightline Avenue  
Sanford, Florida 32773  
Phone: 407-323-0200  
Fax: 407-321-3804

FAA APPROVED REPAIR STATION #OE4R411M

### INFORMATIONAL I.D.

A/C Serial No. 5176  
A/C Reg. No. N556VT W/O No. 80151-1  
Date 10/31/22  
Model No. AI-LCD142HPA  
Part No. 05990965  
Serial No. 05990965

☐ Removed for installation/inspection

REMOVED FOR  
NEW INSTALL

Signature

BL

REV. E ESN  
DO-160C EN/CAT A 1XXXXXX  
S/N  
PIN  
AI-LCD142HPA  
05990965  
CUST PIN  
WT. 6.60 LBS. DATE 5/10/99  
AUDIO INTERNATIONAL  
North Little Rock, AR

**PPNS LLC**

4309 General Aviation Av.  
Austin, Texas 78719

**Airframe Entry**

Maintenance Center (B03)

Reg Number: N556VT  
Bombardier CL-600-2B16  
S/N5176

Date: 1/29/2023

ACTT: 5006.3  
ACTLL: 4270

The above aircraft removed from registration N556VT on 1/29/2023. Removed the component listed for Upgrade no defaults found.

Description: 14.2 Inch Monitor Display

P/N: AI-LCD142HPA

S/N: 05990965

Aircraft was not involved with any accidents.  
to the best of my knowledge:

This Part has not been involved in an Accident, Used in a Military Aircraft or  
Subject to Extreme Heat or Stress.

A and P 3681250

*Abram Sissons*





