

FORM NO.  
RO/001

**DOWTY** ROTOL INCORPORATED  
FAA APPROVED REPAIR  
STATION NO. 1295

SULLY ROAD, P.O. BOX 5000  
STERLING, VA. 22170

PROPELLERS, ACCESSORIES

REPAIRED

~~XXXXXXXXXX~~

Date Feb. 24, 1970 W.O. WAR-826  
Part Name Valve  
Model or Type 288455B  
Serial No. U170  
Inspected by *[Signature]*  
Owner Falcon Jet Corp.  
Address

### OVERHAUL / REPAIR DATA

P/N: 288455B S/N: U170 W/O: WAR 826  
 Overhauled  Repaired  Checked O.K. T.S. 695 hr.  
Findings: Found Flow Rate To Be Extreme.

Work Accomplished: Replaced Restrictor Washer (288475)  
And Tested Unit (Tests 2(A), 2(B), 2(C), 2(D), 3(A), And 3(B)(2)  
Of Messier Manual 29-09-25, Unit Tested Normal.

Mods. and S.B. Accomplished: None

Mechanic: W. Vetter Insp. *[Signature]*

DOWTY ROTOL, INC.

C.R.S. #1295

RO/322

(OVER FOR ADDITIONAL INFORMATION)