

NOTICE 28 VOLT

TUNE/IDENT LAMP

CONTROL TYPE CTL-90 / TSO C74c  
PN 622-4527- 016 . 1.1 LB S/N 9416  
Collins Avionics Divisions/Rockwell International  
Cedar Rapids, IA 52498 USA/Mfd Melbourne, FL

Central Texas Avionics, Inc.

217 Corsair Drive  
Georgetown, TX 78628  
(512) 868-8484 Fax (512) 869-7985  
FAA Repair Station # C84R586N

### REPAIRABLE PART

Component: TXP-control Serial #: 9416

Part/Model #: 622-4527-016

Work Order #: \_\_\_\_\_

Date: 9-25-07

Comments: Removed for install