

**WARNING - UNCOORDINATED MANEUVERS , INCLUDING
SIDE SLIPS OF 30 SECONDS OR MORE , FOR ANY
REASON , AND FAST TAXI TURNS JUST PRIOR TO
TAKE-OFF CAN CAUSE LOSS OF POWER IF FUEL
TANKS IN USE ARE LESS THAN 1/4 FULL**