

ATA

NEVITT AIRCRAFT INC. — SERVICEABLE PARTS TAG



Name Switch Rotary Flap PN C# 402-3

SN 9428 TSO _____ Date Rec. _____

Vendor _____ W.O. _____

Shelf Life _____ Insp. _____

New O/H Repaired Bench ck Removed Time Rem.

Remarks Replaced 3 micro switches (note in part form needs transfer after adj)

A/C 2850H TAT _____ TC _____ Hobbs _____

Reason for Removal Replaced w/ new -

Position FLAP Off SN _____ Mech. APP Bill M
1-11-2020

Date of Installation 1-11-2020