




MS3126F10-68

#16 contacts, use
#12 contacts, use S3/CL-4 die
Or Burndy BANDOMATIC - fully automatic
crimping machine
Or MS3191-A type Hand Tool

FIG. 1