


WO: C26462826



Component Condition Report

OSP Order No 1940565

OSP Creation Date 2019-10-28

Warranty(Y/N) N

Vendor

Nomenclature FLUX VALVE

Supplier Location

Item 2594484

Serial No

Qty 1

Ref Serial No 94090984

ATA 34

Position

AC TYPE(NHA ITEM NO) CTN_AC

HL NO(NHA Serial No) HL7501

Install Date

Removal Date 2019-10-18

ESDS Item

UN Number

Weight .55KG

Critical Stock Control

Cage Code 07187

TSI/CSI	Hours	Cycles
TSO/CSO	Hours	Cycles

TST/CST	Hours	Cycles
TOT/TOC	Hours	Cycles

Reason For Return :
HDG ERROR-50 DEGREES MORE OVER

Shop Finding & Part Condition :
EXTERNAL NORMAL

Work Requirement by KAL :

REP

Notification of Requirement:

SB Requirement :

Revision Free Of Charge Attrition Base

Information to Vendor :

IN CASE THAT THE UNIT IS REQUIRED TO BE MODIFIED AND/OR IMPROVED BY A CERTAIN SB, PLEASE DO NOT
DE-MODIFY BY ANY PRE-SB UNLESS CERTAIN NOTICE IS PROVIDED FROM KAL

940915:FT

Warranty Statements, If Any :

CONTACT POINT(e-Mail Address) : ICNMCPG@KOREANAIR.COM