

OVERHAUL / REPAIR DATA

P/N: 288453 B S/N: 36 W/O: 5-13775

Overhauled Repaired Checked O.K. T.S.O. 0

Findings: Normal wear

Work Accomplished: Installed New Restriction Washers (288467 And A80670) To Modify Unit From 288455B To 288453B Rest of As Per Customer's Instructions, Replaced Nameplate (over)

Mods. and S.B. Accomplished: None

Mechanic: W. Felton Insp: [Signature]

C.R.S. #1295

DOWTY ROTOL, INC.
(OVER FOR ADDITIONAL INFORMATION)

RO/322

FORM NO.
RO7001

DOWTY ROTOL, INCORPORATED

FAA APPROVED REPAIR
STATION NO. 1295

5111 ROAD, P.O. BOX 5000
STERLING, VA. 22170

PROPELLERS, ACCESSORIES

OVERHAUL

Date Mar. 21, 1978 S-13775
Part Name Restrictor
Model or Type 288453B
Serial No. 36
Inspected by [Signature]
Owner Falcon Jet Corp.
Address _____