

AOG Reaction526 Aviator Drive
Fort Worth, TX 76179-5425F.A.A. REPAIR STATION TU1R519K
(817) 439-0700
FAX (817) 439-9700

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 151650	
4. Organization Name and Address: AOG Reaction, Inc. 526 Aviator Drive, Fort Worth, TX 76179 (TU1R519K)						5. Work Order/Contract/Invoice Number: W.O.# 151650	
6. Item:	7. Description:	8. Part Number:	9. Eligibility*:	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:	
1	Temp Switch Honeywell	975-0145-007	N/A	1	870	OVERHAULED	
13. Remarks: OVERHAULED in accordance with CMM 21-44-01, REV 4, dated Jan 11 2002 DISASSEMBLED, CLEANED, REPLACED TEMP SWITCH, RETESTED OK See Teardown/Analysis Report for further details and back side of form for User/Installer Responsibilities statements Certifies that the work specified in Blocks 12/13 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.4164.							
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work the items are approved for return to service.			
15. Authorized Signature: N/A		16. Approval/Authorization No: N/A		20. Authorized Signature: <i>Edward Roberts</i>		21. Approval Certificate No: TU1R519K	
17. Name (Typed or Printed): N/A		18. Date (m d y): N/A		22. Name (Typed or Printed): Edward Roberts		23. Date (m d y): May 09 2012	

TEARDOWN/ANALYSIS REPORT

Customer: Aerospace Service, Inc.
Customer Agent: Rosanne Guarcello
Part Number: 975-0145-007
Part Nomenclature: Temp Switch
Manufacturer: Honeywell
Removed From: AEROSPACE SERVICE STOCK
Time on Part: NTC
Defect Reported: AIR WORTHINESS INSPECTION, ZERO TIME
Defect Confirmed?: N/A
Shop Inspection/Test Findings: FAILED TEST
Work Accomplished: OPERATED OUT OF SPEC

Serial number: 870
ATA Code: 21

AD Notes, Service Bulletins Applicable: None

Work Accomplished: OVERHAULED in accordance with CMM 21-44-01, REV 4, dated Jan 11 2002
DISASSEMBLED, CLEANED, REPLACED TEMP SWITCH, RETESTED OK

Customer's RO: R6001309
Date received: Apr/20/2012

526 Aviator Drive • Fort Worth, TX 76179-5425 • (817) 439-0700 • FAX (817) 439-9700