

CHERRY[®] Brand Aerospace Fasteners

DO NOT OPEN BAG UNTIL FASTENERS ARE TO BE USED

Contents may become contaminated or lose their lubricant,
which may affect installation performance.

**IMPORTANT: BLIND FASTENERS ARE NOT ALWAYS INTERCHANGEABLE WITH
NON-BLIND FASTENERS. CONSULT WITH THE AIRCRAFT ORIGINAL EQUIPMENT
MANUFACTURER FOR PROPER APPLICATION OF THIS PRODUCT.**

ACCEPT NO SUBSTITUTES[™]

2009 00 248

CR3213-6-05 FAA-TSO-C148

LOT # 87214274



Hole .192 .196
Grip .251 .312



CHERRYMAX

QTY

100

May 2009

**ALSO IN FULL COMPLIANCE WITH THE
FOLLOWING NON-TSO PART NUMBER(S)**

- | | |
|-----------------|---------------|
| NAS9301B-6-05 | CAN43078B6-5 |
| NAS9301BNS-6-05 | MBBN3012L4805 |
| M7885/2-6-05 | B0207005-6-05 |
| ASNA0078A605 | S2906-6-5 |



**CHERRY[®]
AEROSPACE**

24 East Warner Avenue, Box 2157 • Santa Ana, CA 92707-0157 U.S.A.
www.cherryaerospace.com • phone: +1 714-545-5511
FSCM 11815