





DO NOT OPEN BAG UNTIL FASTENERS ARE TO BE USED
Contents may become contaminated or lose lubrication which may affect their installation performance.

WARNING:
BLIND FASTENERS ARE NOT ALWAYS INTERCHANGEABLE WITH NON-BLIND FASTENERS. CONSULT WITH THE AIRCRAFT ORIGINAL EQUIPMENT MANUFACTURER FOR PROPER APPLICATION OF THIS PRODUCT.

ACCEPT NO SUBSTITUTES™

CR2538P-6-06	FAA-TSO-C148

LOT # 86152337



Hole .205 .209

Grip .313 .375

Qty.



100

SEP/02

PAR90

CHERRY LOCK™

ALSO IN FULL COMPLIANCE WITH THE
FOLLOWING NON-TSO PART NUMBER(S)

NAS1739MW6-6

SL4129-6-6

TEXTRON Aerospace Fasteners

A Unit of Textron Fastening Systems
1224 East Warner Ave., Box 2157
Santa Ana, CA 92707-0157
Phone: 714-545-6511

www.taf.textron.com

FSCM 11815