




KC 192 FLIGHT COMPUTER S/N: 5 3 1 6 8
MAX.DC VOLTS/CURRENT 28V/0.9A
WT. 2.5lbs TSO C9c, C52a P/N 065-0042-03
DO 160A ENV.CAT./C101/A/SP/XXXXXXZBBB
BENDIX/KING GEN.AVIATION AVIONICS DIV.
KING RADIO CORPORATION OLATHE, KANSAS U.S.A. 66062

MODS.



MID-CONTINENT INSTRUMENT CO., INC.
PART NON-CONFORMANCE TAG

Part #: 065-0042-03

Part Name: flight computer

W.O. 331572 Qty _____ NMR # _____

Reason: would not pass pre flight test. Replaced logic processor, unit now passes pre flight test but no navigation, modes will engage

Originator Giner Martin Date 5/11/18

FORM QC-17R
6019038-1 Rev. B

**BE INSTALLED IN ACCORDANCE
WITH THE STC**

 **Capital Avionics**
Quality, Service, Innovation
www.capitalavionics.com

3701 Hartsfield Road FAA CRS# NS4R399M
Tallahassee, FL 32303 EASA.145.4290

Work Order #: 21743

Inspected ☐ Repaired ☒ Overhauled ☐

INTERMITTENT
FAIL PFT
224-J

