

**CAMTRONICS**  
A HEICO COMPANY

**Camtronics LLC**  
122 West Beechcraft Dr  
Tulsa, OK 74132  
USA  
Ph: (918) 299-5148, Fax: (918) 298-1060  
FAA CRS No : D8XR913Y

**BER / Scrap Notice**

Work Order : TCA4153  
PN : 7514081-911  
Serial : ANE41560  
Date Printed : 6/25/2025

**To:**  
PPNS LLC  
11 BEE TREE CIRCLE  
ROCKPORT, TX 78382  
USA

**Ship To:**  
PIUS PARTS  
11 BEE TREE CIRCLE  
ROCKPORT, TX 78382  
USA

RO : P00448  
PN : 7514081-911

Code : PPNS  
Descr : TCAS ANTENNA

Work Scope : RAI  
Qty : 1

**Service Performed :**

**SYMPTOM- PRELIMINARY**

Unit was visually inspected and exhibits wear and tear typical of in service condition.  
**FAULT-OVERHAUL**

Unit was inspected to the level necessary to isolate external faults. Unit exhibited wear, tear, and sealant around the mounting holes and edges around the unit (i.e., worn exterior radome and paint.) typical of in-service conditions.

Radome separation from adapter plate, very high possibility of water intrusion. Reason or cause of antenna failure. Overhaul required IAW CAM-4081.

**ACTION-SCRAP**

**\*\*Due to PCB degradation, unit is considered non-repairable and cannot be returned to service IAW CAM-4081. Recommend scrap\*\***

**Bill Of Materials (BOM) :**

PN	Description	Qty Needed	CD	Disposition
7514081-911-OH KIT	OVERHAUL KIT	0	NE	INOP

*Edw*







**CAUTION**  
SEALING CRITICAL  
REFER TO MANUAL  
FOR MOUNTING PROCEDURE

4153

8457

15

