	Civil Aviation ity/Country:	2.				3. Form Tracking Number:
	nited States	100	HORIZED REL A Form 8130–3, AIRWO			WO-304557
4 Organizati	on Name and Addres	6.				& Worth On Lot 6
4. Organizati	on Name and Address	Miller	nnium International, LL 237 NW Blue Parkway ee's Summit MO 64063		Tel: 816-524-777 Fax: 816-554-004	P00554
6. Item:	7. Description:		8. Part Number:	9. Quantity:	ATION: M7XR967	
o. nem.	7. Description.		o. Tart Admitet.	7. Quantity.	10. Seriai Aumber	: II. Status/ Work:
1	DISPLAY	UNIT	7014300-901	1	00117934	REPAIRED
12. Remarks:						
Unit Repai	red IAW CMM		A09-1147-043	REV#	1:7	REV DATE: 08/Feb/2019
NO AIRWOI	RTHINESS DIRECT	VES APPLY				
Millennium respect to the 13a. Certifies	International, LLC at work the compo the items identified	certifies tha ment is consid	dered ready for release to	ock 11/12 was carried service under EASA	out in accordance Part-145 Approval	with EASA Part-145 and in Number: EASA 145.4680. her regulation specified in Block 12
□ No	proved design data an a-approved design da		Block 12.		12 was accomplished art 43 and in respect to	
13b. Author	rized Signature:	13c. Appro	val/Authorization No.: 1	4b. Authorized Signatur	re: V	14c. Approval/Certificate No.: M7XR967N
13d. Name (Typed or Printed):	13e. Date (0	ld/mmm/yyyy): 1	4d. Name (Typed or Pri	nted):	14e. Date (dd/mmm/yyyy):
			的學院機能	Wade E.	. Drake	28/Aug/2025
			User/Installe	r Responsibilities		
		the existence of	of this document alone does		ute authority to insta	ll the aircraft
of the countr	er/installer perform y specified in Block	, it is essential	dance with the national regu that the user/installer ensur hiness authority of the count	es that his/her airworthin		t than the airworthiness authority aircraft

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown. FAA Form 8130-3 (02-14)

NSN: 0052-00-012-9005

WO-304557



Millennium International, LLC

237 NW Blue Parkway Lee's Summit, MO 64063 816.524.7777 www.avionics411.com

 Start Date: 07/28/2025
 PN: 7014300-901
 Cust Ref: P00554

 Inspection Date: 08/28/2025
 SN: 00117934
 Action: REPAIRED

Description: DISPLAY UNIT Model: DU870 Quantity: 1

PN	Description	QTY
7018638-903	CRT ASSEMBLY	1
7018704-903	HVPS	1
EZ-1355-12	COVER	1
7018605-901	A3 VIDEO CCA	1
TY232M	STRAP	1
8MA-A-140/60	TEMP INDICATOR	1
8MA-A-180/82	TEMP INDICATOR	1

TECHNICAL PUBLICATIONS

CMM,	A09-1147-043	REV #:7	REV DATE: 08/Feb/2019
------	--------------	---------	-----------------------

MAINTENANCE RELEASE CRS# M7XR967N

The aircraft, airframe, engine, or appliance identified was repaired and inspected in accordance with current regulations of the FAA and is approved for return to continu

WO-304557



Millennium International, LLC

237 NW Blue Parkway Lee's Summit, MO 64063 816.524.7777 www.avionics411.com

Start Date: 07/28/2025	PN: 7014300-901	Cust Ref: P00554	
Inspection Date: 08/28/2025	SN : 00117934	Action: REPAIRED	
Description: DISPLAY UNIT	Model: DU870	Quantity: 1	

WARRANTY DETAILS **CUSTOMER INFORMATION** PPNS LLC (DBA PIUS PARTS) Warranty: Warranty N/A 11 Bee Tree Circle Resolution: Rockport, TX 78382 USA **OEM Intact** Warranty Contact: Quotes Seals: Email: rfq@piusparts.com

CUSTOMER UNIT INFORMATION

Customer Complaint:	SCREEN GOES BLANK	
Complaint Verification:	YES	
Customer Instructions:		
Incoming Mods:	A-L	La Padde Care City
Outgoing Mods:	A-P, S, T	
Incoming Hobbs:	N/A	
Outgoing Hobbs:	N/A	

EVALUATION

Findings:

Removed Case and performed full conformity inspection finding no discrepancies. Troubleshooting found unit fails functional testing and requires disassembly, cleaning, replacement of parts listed below, incorporation of Service bulletins listed below, alignment as required, reassembly, extended thermal and environmental testing as required, and final testing in accordance with approved data. SB 7014300-22-19 (Mod M) (CASE) SB 7014300-22-14 (Mod N) (HVPS) SB 7014300-22-15 (Mod P) (A3) SB 7014300-22-17 (Mod S) (LVPS) SB 7014300-22-01 (Mod T) (LVPS)

Hidden Damage:

N/A

CORRECTIVE ACTIONS

Corrective Actions:

Disassembled, cleaned, replaced parts listed, incorporated Service Bulletins listed as required, reassembled, aligned and final tested in accordance with approved data. The unit found Airworthy.

Technician: Matt Gray

PARTS

PN	Description	QTY
7018613-901	LVPS ASSEMBLY	1