



Model Cisco: 1841



US: 5B1IS01B0063  
IC: 2461B-00114  
SCT: TEDCIC106-719



TNY-CISCO1841

**TELEPERMIT**  
This Cisco 1841  
Integrated Services Router  
Chassis may be connected  
to the Telecom Network  
PTC 217 / 04 / 003



(01)07898362231384

Complies with  
IDA Standards  
DA00518



Product contains cryptographic  
features and is subject to US and  
local laws governing import,  
export, transfer and use.



<http://cisco-returns.com>

這是甲類資訊產品，在居住環境中使用時，可能會造成射頻干擾，在這情況下，使用者會被要求採取某些適當的對策。



この装置は、クラス A 情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。  
VCCI-A

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Warning!  
This is a class A product. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.

This Class A digital apparatus complies with Canadian ICES-003.  
Cet appareil numérique de la classe A est conforme à la norme NMB-003 du Canada.

Apparaten skall anslutas till jordat nättutag.

47-21294-01 Rev B0

PID VID:



CISCO1841 V05

CLEI:



IPM7W00CRA

SN:




SN: FTX133382WL

TAN:



800-23434-06 E0

Cisco Systems, Inc.  
Country of Origin U.S.A.



US

14AUG2009

**PARTS IDENTIFICATION TAG**

Removed From N552 HA

Description R/H Aft Router Removed from lower

P/N \_\_\_\_\_ S/N \_\_\_\_\_

Notes Inventory Cab Colset

Location in removal book. Page # 15 Item # 6

WO # 181102

Removed By J. Blanchard

Date: 12-13-18

AQP 180-1