

Repaired/Overhauled by:
43181

Replacement
Plate

IGNITION EXCITER

TYPE
CUST. NO.
P.N. REV.
SERIAL

TX109
3041641-01
9049770-3 C
NNA05235846

INPUT
DUTY
REPAIR
STA. NO.

10-30 VDC
1.75 MAX AVG.
CONT

4XMR492D

Manufactured By: UNISON INDUSTRIES 59501 Jacksonville, FL USA

