

O'Brien Enterprises

2420 E. 28th Street, Unit 2
Signal Hill, California 90755
Tel: 562-988-9546
Email: sobrienenterprises@gmail.com
F.A.A. # QK3R792L

WORK ORDER NO. 29798

INSPECTION AND TEARDOWN REPORT

Customer Pius Parts Date Received 24SEP2025
 Address Rockport TX Units Received this P.O. 2
 Unit 1 of 2 Units
 Customer P.O. # P00673 Assembly Serial # 14447 C1
 Part Number 32700015 Cylinder Serial # _____
 Other Part Number N/A Other: _____
 Manufacturer: Kidde HTL/PacSci AMEREX Other _____
 Description: Fire Extinguisher Other _____

CUSTOMER REQUESTS

Overhaul Weight and Leak Test
 Hydrostatic Test Inspect interior
 Repair Other _____
 Refill _____
 Inspect and test pressure switch Yes No N/A

INITIAL INSPECTION

Date of Mfg. 08-1995 DOT Rating: 4D _____ 7945- 700 Other _____
 Last Overhaul 06-2020 Capacity: 60 C.I. 86 C.I. 90 C.I. 125 C.I.
 #1 Cartridge Date: 09 / 2019 None 195 C.I. 224 C.I. Other Cap. _____
 #2 Cartridge Date: 09 / 2019 None Test P.S.I. 1600 1800 2000 2100 2400 3000 Other _____
 #3 Cartridge Date: _____ / _____ None Received: Full Empty Fired Low P.S.I.

INITIAL INSPECTION ANALYSIS

Parts Missing: None Cartridge(s) Discharge Outlet(s) Safety Cap(s) Halon/N2 Other: _____
 Additional Parts Received: None Safety Caps Strap/Clamp Other _____
 Exterior Condition: Good Fair Poor Other 1 cartridge damaged in transit
 Interior Inspection: Pass Fail Hidden Damage: Yes No Comment _____
 Repairable: Yes No BER/Scrap: Yes No
 Serviced per Mfg: HTL/PacSci Kidde NFPA10 Other _____
 Serviced I.A.W. Customer Procedures Manual: Yes No Manual # 26-20-202 Rev. Date 08-01-2013
 Other _____ Rev. # 8-1-2019
 Investigate A.D. Activity: Yes No By Sid O Findings: No Activity Other: _____

CORRECTIVE ACTIONS

Overhauled IAW Mfg Specs Inspect Interior Scope of Work: Inspect and test pressure switch Yes No N/A
 Repaired IAW Mfg Specs Refinish Exterior
 Recharge - Wt. and/or Leak Test No Work Done
 Hydrostatic Test IAW DOT/CFR49, PART 180.2