

|     |    |    |    |
|-----|----|----|----|
| MOD | 1  |    |    |
|     | 4  | 5  | 6  |
| 7   | 8  | 9  | 10 |
| 11  | 12 | 13 | 14 |
| 15  | 16 | 17 | 18 |
| 19  | 20 |    | 22 |
| 23  | 24 | 25 | 26 |
| 27  | 28 | 29 | 30 |

### HSI PROCESSOR UNIT

TYPE NO. HPU-74      TSO C6c, C52a, C40b  
 DO-160A ENV CAT.    F2B/JY/XXXXXXA/BZ/AZA

WT **4.5** LB      S/N **203**

COLLINS PN 622-6198-**002**

Collins General Aviation Division/Rockwell Collins, Inc.  
 Cedar Rapids, IA 52498 USA/Mfd Melbourne, FL

|    |    |    |    |
|----|----|----|----|
| 31 | 32 | 33 | 34 |
| 35 | 36 | 37 | 38 |
| 39 | 40 | 41 | 42 |
| 43 | 44 | 45 | 46 |
| 47 | 48 | 49 | 50 |
| 51 | 52 | 53 | 54 |
| A  | B  | C  | D  |
| E  | F  | G  | H  |