

7122 1

RESERVOIR ASSEMBLY
CESSNA P/N: 9912103-3
HTL
SIMI VALLEY, CA
HTL S/N: 9985
HTL- P/N: 212940-2
DATE OF MANUFACTURE: 06/19

O'Brien Enterprises

2420 E. 28th Street, Suite 2
Signal Hill, California 90755
Tel: 562-988-9546
Email: sobrienenterprises@gmail.com

WORK ORDER NO. **HY** 27537
D.O.T. #B528

HYDROSTATIC TEST FINDINGS AND COMPLETION REPORT

Customer Pius Parts Date Received 10-24-2025
 Address Rockport TX Units Received this P.O. 1
 P.O. # P 00732 Unit 1 of 1 Units. Page 1 of 2 Pages
 Mfg. Part Number 212940-2 Assembly Serial # 9985
 Other Part Number 9912103-3 Cylinder Serial # 79134 B1
 Manufacturer: Valve P/N # _____
 Kidde HTL/PacSci Scott Puritan B/E Tavco Av-Ox Sota Valve(s) Serial # _____
 Aerox Precise Flight ITT _____ Other _____
 Description: 02 Cylinder N2 Cylinder Other _____

REASON FOR RETURN

Hydrostatic Test Other: _____
 Repair _____
 Recharge _____
 Service Regulator _____

INITIAL INSPECTION

Date of Mfg: 04-2019 Size: 90 C.F. TEST PRESSURE 4800 P.S.I.
 Last Hydro: 07-2022 C.I. Other Information: _____
 DOT Rating: _____
 8162-1850 Non-DOT Cylinder
 3AA1800 Other _____ Full
 3HT1850 Empty
 10945-1850
 3AL _____
 Parts Missing: None Safety Cap(s) Valve Fittings 4 Other: _____
 Additional Parts Received: None Safety Caps Strap/Clamp Mask Other: _____
 Exterior Condition: Good Fair Poor Comments: _____
 Interior Inspection: Pass Fail Hidden Damage: None Comments: _____
 Repairable: Yes No BER/Scrap: Yes No
 Serviced per Mfg: HTL/PacSci Kidde DOT/CFR49 Other: _____
 Serviced I.A.W. Customer Procedures Manual: Yes No Manual # 36-10-03 Rev. 11-2003
 Other: _____

CORRECTIVE ACTION

Hydrostatic Test Scope of Work: _____
 Inspect Interior Repaired
 Refinish Ext. Recharge
 Wt. and/or Leak Test No Work Done
 Inspect and Condemn

