

24 Hours Service
Component Overhaul and Repair, Inc.
1771 Railroad Street, Corona, CA 92626
FAA Repair Station #UL2R217L
WARRANTY VOID IF REMOVED

INTERFACE ADAPTER
MODEL IA-535 **A**
PART NO 501-1406-01
SERIAL NO. 1005
PWR 18 VDC 0.25A
22 VDC 1.0A
WT. 2.6 LB. TSG:C9c
D0-160A ERV CAT
A2ARXXX XABBBA
MODIFICATIONS
1 2 3 4 5 6 7 8 9 10
• • • • • • • • • •
11 12 13 14 15 16 17 18 19 20
• • • • • • • • • •
Component Overhaul and Repair, Inc.
GRAND RAPIDS MICHIGAN - U.S.A.

Component Overhaul and Repair, Inc.
5250 NW 33rd Avenue
Fort Lauderdale, FL 33309
(800) 554-3115
FAA Repair Station #UL2R217L

Supplied By
Airmark International
(800) 420-5349
1771 Railroad Street, Corona, CA 92